Holden Aftersales. Parts News.

Bulletin No: Parts 2013 – R2208
Date: 25th March 2013

Audience: Industry

Subject: New VE Front Rail Sectioning Procedure (PNs: RHS - 92194473 and LHS -

92194474)

Following feedback from the repair industry, Holden has developed a new procedure for the sectioning of the front compartment side rail forward of the strut tower in order to provide an easier option for repairing damage at the very front of the rail on the VE Commodore.

This means that there are now 2 sectioning procedures for the front compartment side rail (Part Numbers: RHS - 92194473 and LHS - 92194474)

1. Front Compartment Side Rail Sectioning (At Strut Tower)

2. Front Compartment Side Rail Sectioning (Forward of Strut Tower)

These procedures apply to the following vehicles:

Vehicle	Model Year
VE / WM	2007-2012
VF / WM	2014 onwards

Please note that there is currently no Holden approved procedure for the replacement of the complete front compartment rail.

These collision repair procedures can be accessed directly by subscription to the following site:

https://www.acdelcotds.com/acdelco/action/subscribehome

If you have any queries regarding the above, please feel free to contact me directly

Paula Hilditch

Collision Business Manager (03) 9647 7579 paula.hilditch@gm.com

