

Holden Aftersales. Parts News.



Bulletin No: Parts 2013 – R2252
Date: 4th June 2013
Audience: Industry
Subject: New repair procedure: VE Front rail Compartment Side Rail Replacement

Following feedback from the repair industry, Holden has developed a procedure for the VE Front Compartment Side Rail Replacement.

This procedure relates to part numbers RHS - 92194473 and LHS - 92194474

These procedures apply to the following vehicles:

Vehicle	Model Year
VE / WM	2007-2012
VF / WM	2014 onwards

These collision repair procedures can be accessed directly by subscription to the following site:

<https://www.acdelcotds.com/acdelco/action/subscribehome>

If you have any queries regarding the above, please feel free to contact me directly:

Paula Hilditch
Collision Business Manager
(03) 9647 7579
paula.hilditch@gm.com

Holden Ltd ABN 006 893 232 Subsidiary of General Motors Corporation

No Holden Dealer or other person is authorised or permitted to make any statement assertion or undertaking in relation to the quality, performance, characteristics, descriptions, or fitness for any purpose of any Holden product or in any Holden product sold by Holden which is at variance with any written statement assertion or undertaking on any of these subjects given or made by Holden Service Parts Operations Division of Holden Ltd, published sales literature, and the company does not accept any liability for any such unauthorised action. Prices are recommended only and are subject to change without notice.

Holden Service Parts Operations: 191 Salmon Street, Port Melbourne, Victoria 3207 Australia Telephone (03) 9647 1111
All correspondence to: H204E / 191 Salmon Street, Port Melbourne, Victoria 3207 Australia Facsimile (03) 9797 7354



Holden.
Genuine Parts.