Important information regarding the BMW Body Level Training program

BMW Body Level Technician PPE requirements.

Required PPE:

Each technician is required to have on arrival at the training event the following items in good usable condition, If a technician arrives with PPE which is not usable they will be sent away and rebooked in a following session incurring full costs for rebooking. Due to COVID19 sharing of any PPE will not be permitted at the venue. These items will also not be available at the venue they will need to be supplied by each student.



Electronic welding helmet with Din settings 9 -13 in working order. Lens must be clean and usable, recommend having spare lens on hand

Battery must not be flat. Spare charged helmet battery is advised.



Heavy grade welding gloves. This type of glove will be worn on the control hand due to excessive heat when welding aluminium.



Rigger style / Tig weld glove. This type of glove will be required for trigger hand, allows better control of handpiece when welding.



If a technician has any sight issues or wears glasses it is recommended they purchase suitable magnification lens which inserts in to the helmet. Sight issue is the biggest cause of technician's failing welding programs.



Welding Jacket must be worn during the weld training, welding sparks are very hot and will burn skin causing sores and infections. Part of this course will be overhead welding with splatter and sparks falling over the student. Always protect yourself by wearing a suitable welding jacket.

Important Notice To all Students and Employers

SAFETY PROCEDURES

All students must have protective work boots and full cover overalls or Industrial Long Sleeved Hard Yakka type shirts and Industrial quality Pants.

These items must be worn at all times whilst the student is in the practical work areas.

PLEASE NOTE: OVERALLS ARE TO BE BOILER SUIT TYPE AS PICTURED BELLOW. NOT SLEEVELESS OR BIB AND BRACE TYPE. NO POLO SHIRTS, T-SHIRTS, SHORTS or TROUSERS SUCH AS WORK UNIFORMS WILL BE ACCEPTED.

SAFETY WEAR AND EQUIPMENT REQUIRED TO ENTER THE WELDING ROOM





BMW Carbon Training

Important Notice To all Students and Employers

I-CAR Australia Academy students must adhere to the academy's OH&S clothing guidelines.

Students are made aware of the appropriate personal safety equipment they are required to wear during all practical tasks on confirmation. All students will again be reminded of the OH&S guidelines at the commencement of each and every training block.

However, even after constant reminders from staff, it is not uncommon that some students still attend without their safety equipment or try to perform their practical tasks without adequate protection.

This is not acceptable practice, and as of the first attendance, all students must follow the guidelines below. Students who fail to bring their personal protective equipment (PPE) to class will be sent home or back to work to collect their PPE before they can commence practical activities. In cases where students repeatedly forget their PPE, their employer will be notified and they will be sent back to work for the rest of the day.

These guidelines are in accordance with Industry standards and are being enforced for the protection of all students. Your understanding and cooperation would be appreciated.

SAFETY PROCEDURES OF THE I-CAR ACADEMY

All students must have protective work boots and full cover overalls or Industrial Long Sleeved Hard Yakka type shirts and Industrial quality Pants.

These items must be worn at all times whilst the student is in the practical work areas.

PLEASE NOTE: OVERALLS ARE TO BE BOILER SUIT TYPE AS PICTURED BELOW. NOT SLEEVELESS OR BIB AND BRACE TYPE. NO POLO SHIRTS, T-SHIRTS, SHORTS or TROUSERS SUCH AS WORK UNIFORMS WILL BE ACCEPTED.



