

# Holden Aftersales.

## Parts News.



**Bulletin No:** Parts 2012 – R2149  
**Date:** 19<sup>th</sup> November 2012  
**Audience:** Industry  
**Subject:** VE Ute Body Side Outer Panel Sectioning

Holden has released three (3) new repair procedures that describe the Holden recommended method for sectional repair of the body-side outer panel rearward of the B-pillar. The sectional repair of the body-side outer panel provides an alternative to full body side assembly replacement for repairing outer panel damage on VE Ute between the B-Pillar and the rear wheel arch.

New part kits have been released for use with these new procedures. The repair kits include a body-side outer panel supplied as a complete panel which must be cut at the sectioning points described in this procedure prior to installation. The kit also includes a number of critical sealers and baffles that should be used according to the correct repair procedure in order to renew the vehicle cabin seal and prevent exhaust gas intrusion into the vehicle cabin. These kits must be used in accordance with the Holden recommended procedure.

Please be aware that for right hand side repairs, a fuel tank filling pipe may also be required in addition to the part kit.

Please note that for damage to the outer rear quarter panel that is isolated to the area rearward of the rear wheel arch, the Holden recommended repair procedure 2355226 - Quarter Panel Replacement (Ute) still applies.

The procedures available for repairer rearward of the B-Pillar are summarized as follows:

Holden Ltd ABN 006 893 232 Subsidiary of General Motors Corporation

No Holden Dealer or other person is authorised or permitted to make any statement assertion or undertaking in relation to the quality, performance, characteristics, descriptions, or fitness for any purpose of any Holden product or in any Holden product sold by Holden which is at variance with any written statement assertion or undertaking on any of these subjects given or made by Holden Service Parts Operations Division of Holden Ltd, published sales literature, and the company does not accept any liability for any such unauthorised action. Prices are recommended only and are subject to change without notice.

**Holden Service Parts Operations:** 191 Salmon Street, Port Melbourne, Victoria 3207 Australia Telephone (03) 9647 1111  
All correspondence to: H204E / 191 Salmon Street, Port Melbourne, Victoria 3207 Australia Facsimile (03) 9797 7354



**Holden.**  
Genuine Parts.

# Holden Aftersales. Parts News.



## Summary

Damaged Area on VE Ute	Model Year	Repair Method Title	Part Numbers Required	Suggested Additional Parts
Body side outer panel damage rearward of the B-Pillar	Up to MY08 - Up to BSI - VIN 324910 or earlier	Body Side Outer Panel Sectioning (Up to BSI - VIN 324910 or earlier - Ute))	92268353 (LHS) or 92268354 (RHS)	92185262 (Fuel tank filling pipe) - RHS only
	MY09 - Up to BSI VE Ute VIN 324910 or earlier	Body Side Outer Panel Sectioning (Up to BSI VE Ute VIN 324910 or earlier		
	MY09 & MY10 onwards - for VIN 324911 and later	Body Side Outer Panel Sectioning (From BSI VE Ute VIN 324911 and later)		
Body side outer panel damage only rearward of the rear wheel arch	All	Quarter Panel Replacement (Ute)	92251932 (LHS) or 92251933 (RHS)	

Access to these collision repair procedures is directly by subscription to the following site:

<https://www.acdelcotds.com/acdelco/action/subscribehome>

If you have any queries regarding the above, please feel free to contact me directly.

### Paula Hilditch

Collision Business Manager

T: +61 (0)3 964 77579

E: paula.hilditch@gm.com

Holden Ltd ABN 006 893 232 Subsidiary of General Motors Corporation

No Holden Dealer or other person is authorised or permitted to make any statement assertion or undertaking in relation to the quality, performance, characteristics, descriptions, or fitness for any purpose of any Holden product or in any Holden product sold by Holden which is at variance with any written statement assertion or undertaking on any of these subjects given or made by Holden Service Parts Operations Division of Holden Ltd, published sales literature, and the company does not accept any liability for any such unauthorised action. Prices are recommended only and are subject to change without notice.

Holden Service Parts Operations: 191 Salmon Street, Port Melbourne, Victoria 3207 Australia Telephone (03) 9647 1111  
All correspondence to: H204E / 191 Salmon Street, Port Melbourne, Victoria 3207 Australia Facsimile (03) 9797 7354



**Holden.**  
Genuine Parts.