



To **Audi Approved Panel Shop Managers**
Audi Approved Panel Shop Estimator
Audi Approved Panel Shop Foreman

ADAS Calibration Requirements

Dear Colleagues,

From Jan 1st 2018 ADAS systems such as AEB, Lane Departure Warning and cross-traffic assist will be evaluated and included in the calculation of the vehicles ANCAP score.

<http://www.ancap.com.au/safety-ratings-explained>

Advanced Driver Assistance Systems (ADAS) often require post-repair calibrations after repair work has been carried out not only to or around the area of the ADAS sensors but also to other seemingly non-related systems or areas. To ensure all passive and active safety systems function correctly the calibrations must be performed if required, failure to do so could cause a negative effect on the occupant's safety and the vehicles ANCAP score.

To assist Audi Approved Repairer to clearly identify when an ADAS sensor is fitted and if calibration is required, a guide has been developed. This guide will be updated periodically as new sensor technology's and repair methods are introduced.

The guide can be found in the AudiPortal in the following location:

AudiPortal → Training Documents → ADAS Calibration Guide

It is also imperative that the latest information available through ElsaPro is consulted and followed during every vehicle repair.

Kind regards,

Gareth Wright
Product Support Specialist

Audi Australia

ABN: 86 077 092 776
895 South Dowling Street
Zetland NSW 2017
Australia
Telephone +61 2 9695 6200
Facsimile +61 2 9695 6222
audi.com.au