Recommended GM Steel Reparability Matrix

Steel ID Stamping	Grade	GM Specifications	Welding Method			Cold repair	Use of Heat for repair	Temp. Range	Maximum Heat
Symbols ⁴									
					MIG Braze ¹				
	Mild Steel	GM6409M (all) GMW2M (all)	Yes	Yes	Yes	Yes ²	Yes	Up to 1200 °F (650 °C)	90 sec. x 2
	Laminate steel		NO	Yes	NO	Yes ²	NO		
	Bake Hardened	GM6093M (all) GMW3032M(all)	Yes	Yes	Yes	Yes²	Yes	Up to 1200 °F (650 °C)	90 sec. x 2
	Solid Solution- Strengthened		Yes		Yes	Yes ²	Yes	Up to 1200 °F (650 °C)	90 sec. x 2
	High Strength, Low Alloy	GM6208M (all), GM6218M(all), GM3032M(HR CR grades)	Yes	Yes	Yes	Yes ²	Yes	Up to 1200F (650°C)	90 sec. x 2
	Dual Phase ≤779 MPA min. UTS	GMW3032M (HR DP and CR DP grades) GMW3399M (HR DP, CR DP and HR HE grades with TS≤779MPa)	Yes	Yes	Yes	Yes ²	No	N/A	N/A
DPX 😂	Dual Phase ≥780 MPA min. UTS ³	GMW3399M(all other HR DP, CR DP	Yes ³	Yes	Yes ³	No	No	N/A	N/A
≥780MPA		and HR HE Grades)							
MP ⋒	UHSS ³ Martensitic ³	GM6123M (all) GMW3399M (all MS	Yes ³	Yes	Yes ³	No	No	N/A	N/A
M 😂	Boron (PHS/Hot- Stamped) ³	& MP grades) GMW14400							
B ⊱									

¹ Must use 8mm x16mm slotted holes

Note: GM does not endorse repair of door impact beams.

Dual phase Steels up to DP 780 may be sectioned with an approved service procedure.

² Cold repairs can be performed if damage excludes kinks.

³ Mig Plug Only, NO STITCH WELDING. These steels may NOT be used as a backer for stitch welding. NOTE. Deviation from this chart is ONLY allowed if there has been a crash analysis completed by the Design Engineer and a Service procedure has been written. NOTE number values are tensile strength

⁴ ISO Symbol for repair.

Descriptions of GM Steel

Descriptions of divisited			1	
Grade	Alloy Content	Heat Treatment	Typical Applications	Comments
Mild Steel, Bake Hardened, Solid	Low	Fully	Body Panels (Closures, floor	
Solution Strengthened		Annealed/Dead	pan, dash panel, etc.)	
		Soft	·	
High Strength Low Alloy	Low	Fully	Rails, Structural Members	Strengthened with fine
		Annealed/Dead		particles and small grain
		Soft		size
Dual Phase	Medium	Fully	Rails, Structural Members	15-50% of structure is
	(Manganese,	Annealed/Partially		"hard" martensite
	Silicon,	Hardened		
	Molybdenum,			
	Chromium)			
Ultra High Strength Steel	Low	Fully Hardened	Rocker reinforcements, door	100% of structure is
(Martensitic, Boron)			beams, bumper beams	"hard" martensite
TRIP (Transformation Induced	High	Fully	TBD	Complex microstructure
Plasticity) Steel	(Manganese,	Annealed/Partially		for high strength and
	Phosphorus,	Hardened		ductility
	Silicon,			-
	Aluminum)			